

HISTORIC AMERICAN BUILDINGS SURVEY

Doe Garrison, Newmarket, N.H.

Photographs taken by L.C. Durette around 1937

- NH, 8-NEWM, 1-1 View from South East  
2 " " North East  
3 " " North West  
4 West end corner post and ends of Summer beam  
5 East elevation - corner post  
6 Sill South East corner  
7 Detail South East corner  
8 Detail South East corner post and second floor girt  
9 South West Corner post The moulding has been cut off  
10 North West Corner post and second floor girt  
11 North West Corner post, second floor  
12 North east corner post, second floor  
13 Summer Beam East Elevation Moulded end projecting  
14 End of Summer Beam West elevation  
15 Second Floor Girt above Front door  
16 Detail second floor girt above front door  
17 Stair hall  
18 South east room 1st floor toward previous fireplace  
19 Rear stairs 1st and 2nd floor showing post of chimney girt  
20 Detail of chimney girt and overhang  
21 View looking down rear stairs showing thickness of plank wall 2nd floor  
22 Overhang of exterior of garraion from Leanto.  
23 North entrance Jamb & Head of original entrance door  
24 North entrance Detail right jamb  
25 North entrance Detail left jamb  
26 Mortise holes in girt over window East elevation  
27 Carpenter's V marks for location of rebate, West window, North Ele. 2nd flr.  
28 South window of East room, ~~first~~ first floor.  
29 West Window South Elevation, vertical plank was left jamb of orig. window  
30 Original Opening of West window on north west wall  
31 North west corner post  
32 Post & chimney Girt 2nd floor looking north west  
33 Rear wall 2nd floor showing post of chimney girt  
34 South West corner post 2nd floor  
35 South West corner post  
36 Bottom of South West corner post 2nd floor showing overhang construction  
37 South West Room 2nd floor chimney girt has been cut back to make later plaster wall flush  
38 Stairs to attic  
39 Attic looking east  
40 Attic looking west  
41 Attic floor looking west  
42 Intersection of rear wall girt and intermediate truss

HABS photographs Doe Garrison, Newmarker, N.H. (continued)

- NH, 8-NEWM, 1-43 Intersection of summer beam & chimney girt attic floor  
44 Intersection of summer beam and chimney girt no. 4 attic floor  
45 Intersection of Summer beam & chimney girt no.2 attic floor  
46 Chimney Base looking N.E.  
47 Exterior sheathing from Doe Garrison  
48 Old siding used a second time-chipped to take plaster  
49 Siding found in Doe Garrison